

2026 Water Testing Results - Bandon High School

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Band/Choir Room 23 Faucet	19690300-056CF26A	8/18/2026	1.65
Staff Room Faucet	19690300-058SF26A	8/18/2026	9.06
Staff Room Faucet	19690300-059SF26A	8/18/2026	7.28
Skills Center Faucet	19690300-060CF26A	8/18/2026	2.57
Skills Center Faucet	19690300-061CF26A	8/18/2026	4.67
YTP Faucet	19690300-062CF26A	8/18/2026	16.6
Boys RR (by Room 12) Faucet	19690300-064BF26A	8/18/2026	7.08
Girls RR (by Conference Room) Faucet	19690300-067BF26A	8/18/2026	3.02
Hallway by Computer Lab - Drinking Fountain	19690300-068DW26A	8/18/2026	ND
Boys RR (by Library) Faucet	19690300-069BF26A	8/18/2026	1.39
Boys RR (by Library) Faucet	19690300-070BF26A	8/18/2026	2.16
Boys RR (by Library) Faucet	19690300-071BF26A	8/18/2026	3.09
Girls RR (by Library) Faucet	19690300-072BF26A	8/18/2026	4.07
Girls RR (by Library) Faucet	19690300-073BF26A	8/18/2026	7.85
Girls RR Center W Faucet	19690300-074BF26A	8/18/2026	27.7
Girls RR (by Library) Faucet	19690300-075BF26A	8/18/2026	4.54
Copy Room - Staff Faucet	19690300-076SF26A	8/18/2026	6.78
Staff RR Faucet	19690300-077BF26A	8/18/2026	3.34
Staff RR Faucet	19690300-078BF26A	8/18/2026	4.40
Hallway by Girls RR - Drinking Fountain (new)	19690300-117DW26A	8/18/2026	ND
Any fixture testing at or above the action level of 15 ppb has been immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up			
RETESTS: Will be conducting retests when faucets are ordered and replaced. Expected date 11/01/2026			
ND = Non Detect - Lead level is below the lab's minimum reporting limit of 1.02 ppb			
Shaded results: red = at/above 15 ppb action level; orange = 10-14.99 ppb (EIS recommends addressing). Source: EIS Job No. 2026027, Alexin Analytical Laboratories.			