

2026 Water Testing Results - Harbor Lights Middle School

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Library - Restroom Faucet	19690102-001BF26A	8/18/2026	3.66
Library - Drinking Fountain	19690102-002DW26A	8/18/2026	ND
Library - Restroom Faucet	19690102-003BF26A	8/18/2026	2.71
Library - Staff Faucet	19690102-004SF26A	8/18/2026	1.43
Room 8 Faucet	19690102-006CF26A	8/18/2026	8.37
Room 9 Faucet	19690102-007CF26A	8/18/2026	ND
Room 10 Faucet	19690102-008CF26A	8/18/2026	13.9
Room 11 Faucet	19690102-009CF26A	8/18/2026	2.19
Hallway by Room 11 - Drinking Fountain	19690102-010DW26A	8/18/2026	ND
Room 12 N Faucet	19690102-011CF26A	8/18/2026	22.8
Room 12 S Faucet	19690102-012CF26A	8/18/2026	33.1
Room 13 Faucet	19690102-013CF26A	8/18/2026	ND
Hallway by Room 14 - Drinking Fountain	19690102-014DW26A	8/18/2026	3.93
Room 14 N Faucet	19690102-015CF26A	8/18/2026	17.7
W Wing Boys RR Faucet	19690102-016BF26A	8/18/2026	1.04
W Wing Boys RR Faucet	19690102-017BF26A	8/18/2026	ND
W Wing Boys RR Faucet	19690102-018BF26A	8/18/2026	ND
W Wing Boys RR Faucet	19690102-019BF26A	8/18/2026	ND
W Wing Girls RR 1st Faucet from W	19690102-020BF26A	8/18/2026	19.0
W Wing Girls RR Faucet	19690102-021BF26A	8/18/2026	4.82
W Wing Girls RR Faucet	19690102-022BF26A	8/18/2026	5.04
W Wing Girls RR Faucet	19690102-023BF26A	8/18/2026	3.13
A/V & Copier Room - Staff Faucet	19690102-024SF26A	8/18/2026	5.42
Room 5 Faucet	19690100-025CF26A	8/18/2026	23.2
Room 6 Faucet	19690100-026CF26A	8/18/2026	2.59
Room 3 Faucet	19690100-027CF26A	8/18/2026	14.2
Room 4 Faucet	19690100-028CF26A	8/18/2026	2.71
Room 1 Faucet	19690100-029CF26A	8/18/2026	82.8
Room 2 Faucet	19690100-030CF26A	8/18/2026	16.7
Staff Room 20 - Staff Faucet	19690100-031SF26A	8/18/2026	7.36
E Wing Restrooms - Faucet	19690100-032BF26A	8/18/2026	ND
E Wing Restrooms - Faucet	19690100-033BF26A	8/18/2026	2.39
E Wing Restrooms - Faucet	19690100-034BF26A	8/18/2026	5.46
E Wing by Restrooms - Drinking Fountain	19690100-035DW26A	8/18/2026	1.31
E Wing Restrooms - Faucet	19690100-036BF26A	8/18/2026	8.23
E Wing Boys RR 2nd Faucet from E	19690100-037BF26A	8/18/2026	30.1
Girls' Locker Room - Drinking Fountain (new)	19690100-111DW26A	8/18/2026	1.80
Girls' Locker Room - Faucet (new)	19690100-112BF26A	8/18/2026	3.07
Boys' Locker Room - Drinking Fountain (new)	19690100-113DW26A	8/18/2026	ND
Boys' Locker Room - Faucet (new)	19690100-114BF26A	8/18/2026	1.86
Room 18 Faucet	19690100-115CF26A	8/18/2026	18.2

Any fixture testing at or above the action level of 15 ppb has been immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up

RETESTS : Will be conducting retests when faucets are ordered and replaced.

Expected date 11/01/2026

ND = Non Detect - Lead level is below the lab's minimum reporting limit of 1.02 ppb

Shaded results: red = at/above 15 ppb action level; orange = 10-14.99 ppb (EIS recommends addressing). Source: EIS Job No. 2026027, Alexin Analytical Laboratories.