

# Water Testing Results - Bandon High School

## Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Kitchen Faucet/Kettle	19690218-040KF	11/4/2022	3
Kitchen Faucet/Rinse Sink	19690218-041KF	11/4/2022	2
Kitchen Faucet/Hand Wash	19690218-044KF	11/4/2022	4
North Shop Bathroom Sink Faucet Girls	19690218-050BF	11/4/2022	1
North Shop Bathroom Sink Faucet Boys	19690218-063BF	11/4/2022	5
North Bathroom Sink Faucet Boys	19690218-069BF	11/4/2022	2
North Bathroom Sink Faucet Boys	19690218-070BF	11/4/2022	2
North Bathroom Sink Faucet Girls	19690218-072BF	11/4/2022	1
North Bathroom Sink Faucet Girls	19690218-074BF	11/4/2022	1

Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing

RETESTS			

ND = Non Detect - Lead level is below the set detection limits of 1 ppb